



2002 O2 Binding Recall (January 27, 2003)



Products manufactured and sold in Fall/Winter 2002 (June 2002 - December 2002)

Salt Lake City, Utah (January 27, 2003) - Black Diamond Equipment, LTD. in cooperation with the U.S. Consumer Product Safety Commission (CPSC), voluntarily announced a recall of the O2 Telemark Binding. This recall supercedes the previously announced O2 Telemark Binding Component Replacement Recall announced January 10, 2003.

The limited manufacturing run of Black Diamond O2 Telemark Bindings produced from June 2002 - December 2002 can be identified by the blue color of the toe plate risers and heel levers. All O2 Telemark Bindings with blue toe plate risers and heel levers should be immediately returned for credit to the Black Diamond dealer where the binding was originally purchased.

For help in identifying the product or to find the nearest Black Diamond dealer, please contact Black Diamond Equipment at (801) 278-5533.